



Service Bulletin

File in Section: -

Bulletin No.: PIC5918

Date: October, 2013

PRELIMINARY INFORMATION

Subject: Diagnostic Tips For Auxiliary Battery Testing

Models: 2014 Chevrolet Malibu
Equipped with 2.5L (RPO LKW and KL9)

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

Condition/Concern

Should a technician find it necessary to test or charge the auxiliary battery it will require the use of the EL-50313 Midtronics GR8 Battery Tester/Charger.

Recommendation/Instructions

Please use the following parameters when setting up the EL-50313 (GR8):

Battery Type: AGM

Rated CCA: 155

Note: Updated software for the EL-50313 (GR8) that will revise the test setup path and diagnostic algorithms for the Auxiliary Battery will be available in the near future. At that time a bulletin will be published to assist with the new navigation of the EL-50313 (GR8).

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.