

TO: Service Managers, Parts Managers, and Warranty
Administrators
FROM: Hyundai Motor America
DATE: November 12, 2013
SUBJECT: TSB 13-FL-012: 07-11MY MC Accent P0300-P0304, P0128,
P0328, P0461.

Effective 11/7/13 the subject TSB was issued for performing a software ECU Update for 07-11MY MC Accent incident vehicle with any of the diagnostic codes P0300-P0304, P0128, P0328, P0461.

Please be sure to review TSB 13-FL-012 with the appropriate personnel at the dealership and the following under NOTE:

- This ECU Update is intended for the above DTCs when a related performance issue was not described by the customer and the dealer has confirmed there are no performance issues.
- Parts replaced to address above DTCs are subject to WTC part recall to verify part condition and may be subject to claim chargeback if not verified.

Hyundai appreciates your cooperation and support. Questions may be directed to your District Parts and Service Manager or Warranty HELPREP line at 1-877-446-2922.

HYUNDAI MOTOR AMERICA