

10487403.JPG

date code.JPG

12my smart key date code.pptx

12my smart key.JPG

Reference SSM51797

LR4 / L319

Range Rover / L322

Models Range Rover (All New) / L405

Range Rover Evoque / L538

Range Rover Sport / L320

Title Smart Key cover detaching from the Casing

Category Body

Last modified 14-Jan-2013 00:00:00

Symptom 112000 Latches/Locks & Security

Issue

The outer Cover on the remote key can detach from the casing. See attachment.

Cause

The Root cause was found to be that anti rust oil residue remains on the supplier's tooling at the start of a production run.

Action

The issue is resolved from 18th September 2012. The date date code format and location are different between pre and post 12my vehicles.

Content

Discovery 4/LR4, Range Rover Sport up to 12MY, Range Rover All MY

120918 (year 2012, month September, day 18th), see 2nd attachment for location.

Discovery 4/LR4, Range Rover Sport, 12MY onwards New Range Rover and Evoque

18092012(day 18th, month September, year 2012) see 3rd and 4th attachment.

Please only submit EPQR's for failures after this assured date.

10487403.JPG

date code.JPG

Reference SSM51797

LR4 / L319

Range Rover / L322

Models Range Rover (All New) / L405

Range Rover Evoque / L538

Range Rover Sport / L320

Title Remote Key cover detaching from the Casing

Category Body

Last modified 10-Jan-2013 00:00:00

Symptom 112000 Latches/Locks & Security

Issue: The outer Cover on the remote key can detach from the casing. See attachment.

Cause: The Root cause was found to be that anti rust oil residue remains on the supplier's tooling at the start of a Content production run.

Action: The issue is resolved from date code 120918 (year 2012, month September, day 18th), see 2nd attachment for location. Please only submit EPQR's for failures after this assured date.

112my smart key date code.pdf

212my smart key.JPG

310487403.JPG

3date code.JPG

Reference	SSM51797
Models	Range Rover Sport / L320 Range Rover Evoque / L538 Range Rover (All New) / L405 LR4 / L319 Range Rover / L322
Title	Smart Key cover detaching from the Casing
Category	Electrical
Last modified	03-Jul-2013 00:00:00
Symptom	203000 Basic Electrical
Content	<p><u>Issue</u> The outer cover on the remote key can detach from the casing. See attachment.</p> <p><u>Cause</u> The Root cause was found to be that anti rust oil residue remains on the supplier's tooling at the start of a production run.</p> <p><u>Action</u> The issue is resolved from 18th September 2012. The date code format and location are different between pre and post 12my vehicles. Prior to this please replace parts as per topix.</p> <p><u>Discovery 4/LR4, Range Rover Sport up to 12MY, Range Rover All MY</u> 120918 (year 2012, month September, day 18th), see attachment for location.</p> <p><u>Discovery 4/LR4, Range Rover Sport, 12MY onwards New Range Rover and Evoque</u> 09182012(month September, day18th, year 2012) see attachment for location.</p> <p>Please only submit EPQR's for failures after this assured date, your continued support is appreciated.</p>

11310487403.JPG

113date code.JPG

Reference	SSM51797
Models	Range Rover Sport / L320 LR4 / L319 Range Rover / L322
Title	Smart Key cover detaching from the Casing
Category	Electrical
Last modified	19-Sep-2013 00:00:00
Symptom	203000 Basic Electrical
Content	<p><u>Please note: Refer to technical bulletin LTB00563 which shows a low level repair if this issue is applicable. You should not replace the complete key.</u></p> <p><u>Issue</u> The outer cover on the remote key can detach from the casing. See attachment.</p> <p><u>Cause</u> The Root cause was found to be that anti rust oil residue remains on the supplier's tooling at the start of a production run.</p> <p><u>Action</u> The issue is resolved from 18th September 2012. Please note that the casing is now available as a separate part. Please see technical bulletin LTB00563 and supporting animation SSM 66357.</p> <p><u>Discovery 4/LR4, Range Rover Sport up to 12MY, Range Rover (L322) All</u> 120918 (year 2012, month September, day 18th), see attachment for location.</p> <p>Please only submit EPQR's for failures after this assured date, your continued support is appreciated.</p>

10102012

LEAR:
JLR:B
KGC:
CMIIT

EM 37900



DATE CODE: 101009
LEAR P/N: 5E0B601A7
JLR P/N: AH22-15K601-BF

CMIIT: 2009DJ2121
TRC: TRC/LPD/2009/81
KCC: LER-5E0B6P127

30/01/2012

FRONT



