



# Service Bulletin

File in Section: -

Bulletin No.: PIC5806

Date: February, 2013

## PRELIMINARY INFORMATION

**Subject:** Horn Chirps Entering Vehicle

**Models:** 2012 Buick LaCrosse  
with Keyless Start (RPO BTM)

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

### Condition/Concern

Customers may comment the horn may produce 3 rapid chirps at times when entering vehicle. Concern can happen if ignition is turned to the off position while any door remains open. The next time the customer enters the vehicle with the fob within range, the 3 rapid horn chirps can occur.

### Recommendation/Instructions

Update the BCM with the latest calibration. Reference the Body Control Module Programming and Setup procedure in SI for further details.

### Warranty Information

For vehicles repaired under warranty use:

Labor Operation	Description	Labor Time
N4808	Body Control Module Reprogramming with SPS	Follow Published Labor Time

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.