

Reference SSM64017

Models LR2 / L359  
Range Rover Evoque / L538

Title Smart Key not Found Displayed

Category Electrical

Last modified 28-Mar-2013 00:00:00

Symptom 203000 Basic Electrical

Evoque  
Freelander 2 (13My Onwards)

Issue: Customer reports smart key not found displayed in  
the Instrument Cluster  
Content Cause: TBA

Action: If a customer reports the above concern please  
submit an Epqr as a visit may be required to understand the  
issue.