

OHC Microphone.pdf

Reference	SSM67417
Models	Range Rover (All New) / L405 Range Rover Sport / L494
Title	Telephone microphone poor sound clarity
Category	Electrical
Last modified	30-Jul-2013 00:00:00
Symptom	207000 Entertainment Systems
Content	<p>Issue: A customer may report that when using the infotainment system to make a telephone call the recipient of the call cannot clearly hear the driver of the vehicle.</p> <p>Cause: Overhead console microphone not correctly located in recess.</p> <p>Action: If a customer reports the above concern for a vehicle within the VIN range below as a first step of diagnosis check to see if microphone is correctly located in the overhead console recess and if necessary clip back into position. Please view attachment, image 1 showing overhead console/ microphone location and image 2 showing microphone in an unsecured position.</p> <p>VIN range: All new Range Rover LG100000 to LG130615 All new Range Rover Sport LW300000 to LW303882</p>

