

Reference	SSM67437
Models	Range Rover (All New) / L405 Range Rover Sport / L494
Title	Interior time clock appears to have lost time.
Category	Electrical
Last modified	07-Aug-2013 00:00:00
Symptom	205000 Electrical Accessories
Content	<p>Issue: Reports that the vehicle interior time clock appears to have lost time (usually around 20 minutes) following a Pre Delivery Inspection (PDI) or a service visit.</p> <p>Cause: Normal operation: during any module configuration the time clock will be paused for the duration of module reconfiguration time.</p> <p>Action: Following completion of the PDI or after any module configuration, check and adjust if necessary the time clock setting.</p>