

Reference	SSM67637
Models	Range Rover Sport / L320 LR3 / L319 LR4 / L319 Range Rover / L322
Title	Lack of Cooling From Air Conditioning
Category	Electrical
Last modified	28-Aug-2013 00:00:00
Symptom	208000 Climate Control
Content	<p>Issue: Land Rover engineering have been monitoring reports for lack of cooling from the air conditioning system on higher time in service vehicles, where insufficient performance of the air conditioning compressor has been found to be the root cause of the issue. Compressor Part No. LR010723 & LR013934</p> <p>Action: The compressor supplier in conjunction with Land Rover engineering have made improvements to the compressors to improve their service life and reliability, and two improved compressors have been supplied to parts operations LR010723 Supersedes to LR056364 LR013934 Supersedes to LR056365 Please ensure that the later part number is fitted to any vehicle that is suffering from lack of compressor performance.</p> <p>We would like to thank everyone who contributed to this investigation by submitting EPQR's and returning parts.</p> <p>Please only submit further EPQR's for lack of compressor performance if it is a failure of the new level part</p>