

Reference	SSM67837
Models	LR2 / L359
Title	Primary Door Seal Adrift
Category	Body
Last modified	27-Aug-2013 00:00:00
Symptom	108000 Ext. Trim/Accessories
Content	<p>Issue: There have been reports of Primary Door Seals coming adrift from the body and cannot be robustly refitted to the vehicle</p> <p>Cause: The cause of the parts coming adrift is under investigation but as the parts are a one time fit item refitting them using adhesive or double sided tape will not work</p> <p>Action: If any dealer has a vehicle with the Primary Door Seal coming away from the body:</p> <ol style="list-style-type: none">1 Remove the old part2 Thoroughly clean the body ensuring no adhesive residue is present3 Fit a new part ensuring the the adhesive on the seal is firmly pressed against the body and the part is fully adhered.