

REFERENCE:	Nova Bus Manuals
SECTION:	09 Engine
RS N°:	MQR 7621-515
EFFECTIVE IN PROD.:	L692-46 (2012DE)

APPLICATION DEADLINE: 2014MR21

SUBJECT:	Hydraulic system
JUSTIFICATION:	Hydraulic fluid may leak from loose connections in the radiator compartment, and at the hydraulic manifold block.

LEVEL	DESCRIPTION	DIRECT CHARGES		TIME
		LABOUR	MATERIAL	
1	Retighten the hoses to the specified torque values.	Nova Bus	Nova Bus	30 min
2	-	-	-	-

MATERIAL

QTY	PART N°	REV.	DESCRIPTION	REPLACES PART N°
LEVEL 1				
-	-	-	-	-
LEVEL 2				
-	-	-	-	-

DISPOSAL OF PARTS

REMOVED PARTS ARE:	DISCARDED	RETAINED	-
	-	-	

REVISION HISTORY

REV.	DATE	CHANGE DESCRIPTION	WRITTEN BY
NR	2013MR15	Initial release	Danielle Lacroix

CLIENT	ORDER	ROAD NUMBER		VIN (2NVY/4RKY...)		QTY
		FROM	TO	FROM	TO	
New York City Transit - New York	L643	5895	5895	S92U1B4000143	S92U1B4000143	1
New York City Transit - New York	L670	5771	5894	S92U9B4000147	S92U8C4500060	124
New York City Transit - New York	L670	5770	5770	S92UXC4500061	S92UXC4500061	1
New York City Transit - New York	L681	5896	5986	S92U2C4500023	S92U9C4500164	91
New York City Transit - New York	L681	5253	5283	S92U0C4500165	S92U9C4500195	31
New York City Transit - New York	L692	5284	5328	S92U3C4500158	S92U3C4500239	45

**WARNING**

Follow your internal safety procedures.

PROCEDURE

1.1. Retighten to the torque values indicated in Figure 1. ❖




Figure 1 - Partial View of the Hydraulic System