

MIRROR SWITCH REWORK



Prepared by: Nic Rucker
Field Service Technical Rep.
(256) 499-5433

Approved By: Dan Allen – Chief Engineer

Property and Top Bus Number: DART: 304500



Issue: loose mirror switches

Reason/ cause: switches loose in side dash

Solution: add mirror switch clips

MIRROR SWITCH REWORK



Number of affected buses: 304000 (39001)
304500 (39002-39155)

Estimate repair hours/bus: 30 min

Necessary parts:

537-1613-002	retaining clip	2 per bus
--------------	----------------	-----------

Necessary tools: screw gun, #2 Phillips tip

MIRROR SWITCH REWORK



SAFETY PRECAUTIONS MUST BE FOLLOWED ACCORDING TO ACCEPTED INDUSTRY STANDARDS AND LOCAL/PROPERTY REQUIREMENTS.

1. Park the bus and apply the parking brake.
2. Turn off main battery disconnect switch(es).
3. Remove screws around the side dash. turn side dash on its side



4. Slide the mirror clip in from each side



5. Reinstall side dash
6. Check for completeness of work.
7. Remove all tools from working area.
8. Turn the main battery disconnect switch (es) on.