



PREVOST

**WARRANTY
BULLETIN**

WB13-60

DATE :	OCTOBER 2013	SECTION	07 - Transmission
EXPIRATION:	OCTOBER 2015		
SUBJECT :	VOLVO I-SHIFT SOFTWARE UPDATE – HIGH AND LOW SPLIT SHIFT IMPROVEMENT		

APPLICATION

NOTICE TO SERVICE CENTERS							
<i>Verify vehicle eligibility by checking warranty bulletin status with SAP or via ONLINE WARRANTY SYSTEM available on Service / Warranty tab of Prevost website.</i>							
Model	VIN						
H3-41, H3-45 coaches Model Year : 2010 - 2013	Coaches equipped with I-Shift transmission within the following range From 2PCH33498AC71 1573 up to 2PCH33494DC71 2191 incl.						
X3-45 coaches Model Year : 2010 - 2013	<table border="0" style="width: 100%;"> <tr> <td style="text-align: center;">2PCG33498AC729907</td> <td style="text-align: center;">2PCG33498BC735045</td> </tr> <tr> <td style="text-align: center;">2PCG33491AC729926</td> <td style="text-align: center;">2PCG33496CC735241</td> </tr> <tr> <td style="text-align: center;">2PCG33491BC729992</td> <td style="text-align: center;">2PCG33499DC735316</td> </tr> </table>	2PCG33498 AC729907	2PCG33498 BC735045	2PCG33491 AC729926	2PCG33496 CC735241	2PCG33491 BC729992	2PCG33499 DC735316
2PCG33498 AC729907	2PCG33498 BC735045						
2PCG33491 AC729926	2PCG33496 CC735241						
2PCG33491 BC729992	2PCG33499 DC735316						
<p>This bulletin does not necessarily apply to all the above-mentioned vehicles, some vehicles may have been modified before delivery. The owners of the vehicles affected by this bulletin will be advised by a letter indicating the Vehicle Identification Number (VIN) of each vehicle concerned.</p>							

DESCRIPTION

On the vehicles affected by this bulletin, a software update for the Volvo I-Shift transmission is required.

Software update has for effect to improve the gear change process to avoid clashing and wear on the split gear. This software update is necessary on all I-shift transmission up to but not including serial number 1100**224372**.

CORRECTIVE ACTION

You must contact your nearest Prevost Service Center or Prevost Service Provider to make an appointment in order to have your I-shift transmission software updated with new calibration settings.

PROCEDURE



DANGER

Park vehicle safely, apply parking brake, stop engine and set battery master switch(es) to the OFF position prior to working on the vehicle.

1. Connect Premium Tech Tool (PTT) to the vehicle diagnostics connector.
2. Turn the ignition switch "ON".
3. Once the vehicle has been identified and selected, perform Campaign S6234 MID130, E0407.

WARRANTY

This software update is covered by Prevo's normal warranty. We will reimburse you one hour (1.0) of labor upon receipt of a warranty claim. Please submit claim via our Online Warranty System, available at www.prevo.com (under Service \ Warranty section). Use Claim Type: "Bulletin/Recall" and select "Warranty Bulletin WB13-60".

OTHER

VBC Bulletin	S6234
Fail Code	07.00-3
Defect Code	49
Syst.Cond.	B
Causal Part	3092515

Access all our Service Bulletins on
<http://prevostparts.volvo.com/technicalpublications/en/pub.asp>
or scan the QR-Code with your smart phone.

E-mail us at technicalpublications_prev@volvo.com and type
"ADD" in the subject to receive our warranty bulletins by e-mail.

