



Service Bulletin

PRELIMINARY INFORMATION

Subject: PQC Part Restriction Electric Power Steering Gear

Models: 2013 Buick LaCrosse
with LFX Engine, FWD (RPO F45), and Belt Drive EPS (RPO NJ2)
2014 Chevrolet Impala with (RPO NJ2)
Restricted Part Numbers: 22978626, 22978628, 23153512, and 23153513

This PI was superseded to remove part restriction. Please discard PIC5805B.

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

Condition/Concern

The PQC Part Restriction on the electric power steering gear part numbers: 22978626, 22978628, 23153512, and 23153513 has ended. Thank you for your assistance in collecting data related to these part numbers.

Recommendation/Instructions

These part numbers can now be ordered directly through your parts department.

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION