



# Service Bulletin

## PRELIMINARY INFORMATION

**Subject:** Rotational Noise From The Rear Of The Vehicle When Braking

**Models:** 2012 - 2013 Chevrolet Sonic

*This PI was superseded to communicate repair information. Please discard PIC5781.*

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

### Condition/Concern

A customer may comment that there is rotational noise coming from the rear of the vehicle during brake apply. The noise might be found to be coming from the rear drum brake area.

### Recommendation/Instructions

To correct this concern, replace both Rear Brake Drums (P/N 95224012) and Brake Shoes on both sides of the vehicle (P/N 95145057). Parts are currently available in CCA inventory.

### Parts Information

Part Number	Description	Qty
95224012	Brake Drum	2
95145057	Shoe Kit	1

### Warranty Information

For vehicles repaired under warranty use:

Labor Operation	Description	Labor Time
2430220	Brake Shoe Replacement	Use Published Labor Operation Time

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION