



# Service Bulletin

## PRELIMINARY INFORMATION

**Subject:** Diagnostic Tips For Auxiliary Battery Testing

**Models:** 2014 Chevrolet Malibu  
Equipped with 2.5L (RPO LKW and KL9)

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

### Condition/Concern

Should a technician find it necessary to test or charge the auxiliary battery it will require the use of the EL-50313 Midtronics GR8 Battery Tester/Charger.

### Recommendation/Instructions

Please use the following parameters when setting up the EL-50313 (GR8):

Battery Type: AGM

Rated CCA: 155

**Note:** Updated software for the EL-50313 (GR8) that will revise the test setup path and diagnostic algorithms for the Auxiliary Battery will be available in the near future. At that time a bulletin will be published to assist with the new navigation of the EL-50313 (GR8).

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.

---

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION