



Service Bulletin

PRELIMINARY INFORMATION

Subject: Rear Brake Noise On First Apply

Models: 2013 Buick Encore
2013 Chevrolet Trax (Canada)

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

Condition/Concern

Customers may comment on a rear brake noise that occurs on first brake apply when backing up but can also occur in drive.

Recommendation/Instructions

The correction is to install a dampener P/N 13343688 and bolt P/N 13343686 in place of the rear upper caliper mounting bolts. Refer to SI for bolt removal instructions and torque spec listed in the Brakes section under Rear Disc Brake Pads Replacement.

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION