



Service Bulletin

PRELIMINARY INFORMATION

Subject: Outside Air Temperature Reading May Display Inaccurately

Models: 2014 Chevrolet Camaro

Condition/Concern

Some customers may notice that the ambient air temperature display may be inaccurate in the vehicle's IPC. Upon further diagnosis, technicians may find that no DTCs are set.

Recommendation/Instructions

Important: Do NOT replace any components for this concern.

This concern is caused by a software anomaly inside the IPC.

A new calibration to correct this reading is currently being developed and will be soon be released through TIS2Web.

This PI will be updated with further instructions once the revised calibration becomes available.

Customer Information

Please communicate to the customer that we apologize for this inconvenience and that General Motors is working on a solution for this concern. Once a solution is available, this PI will be updated with additional details - allowing dealership personnel to contact the customer to schedule a service appointment and repair the vehicle.

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION