



Service Bulletin

PRELIMINARY INFORMATION

Subject: Cold Shift Characteristics

Models: 2004-2011 Chevrolet Aveo
2007-2010 Pontiac G3
2005-2009 Pontiac Wave

This PI was superseded to update models and years. Please discard PIP3297A.

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

Condition/Concern

One of the automatic transmission-operating characteristics for the 2004 through 2007 Aveo/Waves when the transmission's fluid temperature is below 15C (59F) is described below.

Recommendation/Instructions

The 4th gear up-shifts are prevented. This is designed to provide improved vehicle emissions and heater performance. Please do not attempt to repair this condition. You can find the transmission's shift control description at the bottom of SI document 1339794 for 2004-2011 Aveo and 2005-2009 Waves.

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION