



Service Bulletin

PRELIMINARY INFORMATION

Subject: Automatic Highbeams Inop

Models: 2013 Cadillac XTS

Condition/Concern

A customer may comment that the Automatic Highbeams are inop.

Recommendation/Instructions

Please advise customer that there is a mis-print in the vehicle Owner's Manual. The 2013 Cadillac XTS does NOT have the automatic highbeam feature.

ADDITIONAL SI KEYWORDS:

auto BCM beam head headlamp high intellibeam KB lamp light module

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION