



Service Bulletin

PRELIMINARY INFORMATION

Subject: No Rear Camera Guideline Selection

Models: 2012-2013 Buick LaCrosse
2012-2013 Chevrolet Equinox
2012-2013 GMC Terrain
2013 Chevrolet Malibu
with Navigation Radio (RPO UYS or UEW)

This PI was superseded to update models, model years and RPOs. Please discard PIC5611.

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

Condition/Concern

No Rear Camera Guideline Selection

Recommendation/Instructions

The owner's manual does not specify that the rear camera Guideline selection is only available on vehicles equipped with RPO UYS or UEW Navigation Radio. Please verify the vehicle has RPO UYS or UEW prior to performing any repairs. If equipped with UYS or UEW verify the Guideline option is turned on. This can be checked by pressing Config, Display, and then select Guidelines.

Warranty Information

For vehicles repaired under warranty use:

Labor Operation	Description	Labor Time
N9999	Electrical Controls - Labor Only	Use Published Labor Operation Time

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION