



Service Bulletin

PRELIMINARY INFORMATION

Subject: Current Or Intermittent DTC P2534

Models: 2008 Cadillac CTS, STS
Equipped with 6L50 (RPO - MYB) Automatic Transmission

This PI was superseded to update recommended field. Please discard PIP4276A.

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

Condition/Concern

Some customers may comment on an illuminated MIL where a DTC P2534 is found in the TCM as a history or active DTC.

Recommendation/Instructions

A revised transmission calibration has been developed to address this DTC. Reprogram the transmission control module (TCM) with updated calibration files using the TIS2WEB Service Programming System (SPS) application. As always, make sure your Tech 2 is updated with the latest software version.

Note: If DTC P2534 continues to set after reprogramming the TCM refer to published diagnostics in Service Information.

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION