

Bulletin No.: PIC5837

Date: Jun-2013

PRELIMINARY INFORMATION

Subject: Diagnostic Aid - Service Stability Message, ABS MIL With C0800 SYM07

Models: 2013 Buick LaCrosse

2013 Buick Regal

2013 Chevrolet Malibu

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

Condition/Concern

A customer or technician may indicate the ABS MIL is illuminated and there is a "Service Stability" message displayed. DTC C0800 Symptom 07 is set along wi any wheel speed sensor: DTC C0035, C0040, C0045 or C0050.

Recommendation/Instructions

Note: Do NOT replace the EBCM for DTC C0800.

The technician should diagnose and repair any wheel speed sensor fault "before" addressing DTC C0800.

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safety. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.

WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION