



# Service Bulletin

## PRELIMINARY INFORMATION

**Subject:** 2013 Chevrolet Spark AISIN Transmission Torque Converter Valve Body And TCM Restriction Has Ended

**Models:** 2013 Chevrolet Spark  
with AISIN (MNG) 80-40LE Transmission

*This PI was superseded to end the PQC restriction. Please discard PIP5058A.*

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

### Condition/Concern

As part of our ongoing quality improvement efforts, the PQC (Product Quality Center) restriction on P/N 25181682, 25188088, 25188306, 25181372 (2013 Chevrolet Spark AISIN transmission) has now ended.

### Recommendation/Instructions

General Motors Engineering would like to thank the dealers that participated in the Chevrolet Spark AISIN transmission restriction.

Dealers can now order the above parts numbers through their parts department. Calls to the PQC are no longer necessary.

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION