



Service Bulletin

PRELIMINARY INFORMATION

Subject: (EREV) Charge Cord Restriction

Models: 2013 Chevrolet Volt

This PI was superseded to remove the Parts Restriction. Please discard PIP5055C.

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

Condition/Concern

Effective 05/30/13 the (EREV) Charge Cord part number 23145307 will no longer be on Restriction through PQC.

Your cooperation with this program has been greatly appreciated.

Recommendation/Instructions

If it is determined that a (EREV) Charge Cord is required, this part can be obtained through CCA.

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION