



# Service Bulletin

## PRELIMINARY INFORMATION

**Subject:** Diagnostic Tip - SES MIL On P2636 Stored Unable To Command Transfer Pump On With Scan Tool

**Models:** 2013 Chevrolet Silverado 3500 Chassis Cab w/ Dual Fuel Tanks  
2013 GMC Sierra 3500 Chassis Cab w/ Dual Fuel Tanks  
with 6.6L Diesel Engine (RPO LML, LMM)

*This PI was superseded to communicate the release of new scan tool software. Please discard PIT5212.*

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

### Condition/Concern

One or several of the following conditions may be present:

- SES MIL with DTC P2636 set
- Technician unable to command the fuel system transfer pump "On" with the scan tool

### Recommendation/Instructions

**Note:** Perform the following BEFORE performing any repairs or replacing any parts.

Verify the scan tool has been updated to S/W Version # 33.003 or higher.

Continue with published diagnostics from that point.

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.

---

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION