



Service Bulletin

PRELIMINARY INFORMATION

Subject: Lifter Noise Or SES Light With A P0300 Set

Models: 2014 Chevrolet Silverado 1500
2014 GMC Sierra 1500
Built with RPO's 5.3L L83

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

Condition/Concern

The customer may experience a lifter noise or SES light with a P0300 set.

Complete the following recommendation if the vehicle was built before July 8th, 2013.

Recommendation/Instructions

Search TIS2WEB and complete the applicable service calibration update when repairing an engine with a concern of a collapsed intake lifter on trucks built prior to July 8th, 2013.

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION