



# Service Bulletin

## PRELIMINARY INFORMATION

**Subject:** Lifter Noise Or SES Light With A P0300 Set

**Models:** 2014 Chevrolet Silverado 1500  
2014 GMC Sierra 1500  
Built with RPO's 5.3L L83

*This PI was superseded to update the labor operation. Please discard PIP5143A.*

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

### Condition/Concern

The customer may experience a lifter noise or SES light with a P0300 set.  
If the vehicle was built before 7/8/2013 the following should be performed.

### Recommendation/Instructions

After repairing an engine with a collapsed intake lifter on an AFM cylinder, check TIS to web for any applicable ECM calibrations.  
This would be for vehicle built before July 8, 2013.

### Warranty Information

For vehicles repaired under warranty use:

| Labor Operation | Description                                  | Labor Time                         |
|-----------------|----------------------------------------------|------------------------------------|
| 2810075         | Engine Control Module Reprogramming with SPS | Use Published Labor Operation Time |

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION