



Service Bulletin

PRELIMINARY INFORMATION

Subject: Information on Front Brake Rotor Cooling Ring Installation

Models: 2014 Chevrolet Corvette Stingray

Condition/Concern

During Pre-Delivery Inspection (PDI) the dealer may find two rings and a coil of safety wire included in the loose items bag and inquire as to what they are and / or how to install them.

Recommendation/Instructions

These are the front brake rotor cooling rings. These rings are NOT to be installed during the PDI process, rather, given to the customer at the time of delivery.

Caution: Do NOT leave rotor cooling rings installed after a track event as this can cause corrosion with long-term use. Rotor cooling rings are for race track use only. Race track driving without the rotor cooling rings may result in brake pedal fade.

More information on the installation of these rotor cooling rings can be found in the Owner Manual "Track Events and Competitive Driving" section under Rotor Cooling Ring.

Warranty Information

For vehicles repaired under warranty use:

There is not a labor time or labor operation associated with this PI. No warranty claim should be filed against this procedure.

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION