

Service Bulletin

PRELIMINARY INFORMATION

Subject: Updated Left and Right I/P Fuse Block Labeling

Models: 2014 Chevrolet Silverado 1500

2014 GMC Sierra 1500

Built Prior to July 26, 2013 in Silao (11th VIN Position = "G")

This PI was superseded to correct part number information. Please discard PIP5224.

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

Condition/Concern

After inspecting the Left and/or Right I/P Fuse Block Labels, it may be noted the numbering is incorrect.

Recommendation/Instructions

Inspect the lower right corner of each label for P/N 23114670 (Left) and/or P/N 23114671 (Right). If these part numbers are found, replace the label(s) with updated label(s): P/N 23207928 (Right) and P/N 23207929 (Left). See photos below of the updated labels:





Parts Information

Part Number	Description	Qty
23207928	I/P Fuse Block Label (Right)	1
23207929	I/P Fuse Block Label (Left)	1

Warranty Information

For vehicles repaired under warranty use:

Labor Operation	Description	Labor Time
1030630	Instrument Panel Fuse Block Access Hole Cover Replacement	Use Published Labor Operation Time

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION