

REFERENCE:	Nova Bus Manuals
SECTION:	04: Front suspension 05: Rear suspension
RS N°:	MQR 7621-711
EFFECTIVE IN PROD.:	–

APPLICATION DEADLINE: 2014OC01
CLAIM REFERENCE NUMBER: –

SUBJECT:	Brake caliper shipping cap.
JUSTIFICATION:	The shipping cap should have been removed in production.

LEVEL	DESCRIPTION	DIRECT CHARGES		TIME
		LABOUR	MATERIAL	
1	Remove the shipping caps from the brake calipers on all axles.	Nova Bus	Nova Bus	10 min
2	–	–	–	–

MATERIAL

QTY	PART N°	REV.	DESCRIPTION	REPLACES PART N°
LEVEL 1				
–	–	–	–	–
LEVEL 2				
–	–	–	–	–

DISPOSAL OF PARTS

REMOVED PARTS ARE:	DISCARDED	RETAINED	–
	–	–	

REVISION HISTORY

REV.	DATE	CHANGE DESCRIPTION	WRITTEN BY
NR	2013OC10	Initial release	Bertrand Plouffe

CLIENT	ORDER	ROAD NUMBER		VIN (2NVY/4RKY...)		QTY
		FROM	TO	FROM	TO	
Houston - Texas	L755	1519	1519	S92U5D4500342	S92U5D4500342	1

**WARNING**

Follow your internal safety procedures.

PROCEDURE

- 1.1. Raise the vehicle.

**CAUTION**

For information on hoisting and towing of the vehicle, see section 18: HOISTING AND TOWING in the Nova Bus maintenance manual. Respect your internal safety procedures. Use appropriate hoisting equipment for your protection.

- 1.2. Locate the six brake calipers.
- 1.3. Locate the shipping caps on each calipers. See Figure 1. The caps can be identified by their green color, but they may have been painted black.




Figure 1 - Shipping Cap Location

- 1.4. Remove the six shipping caps. Discard the caps.
- 1.5. Lower the vehicle.
- 1.6. The vehicle may be returned to service. ❖