



Field Service Bulletin

Release: June 21, 2013

Subject: Ford E350/450 gas engine with secondary alternator

Origin: Fred Birchfield

Wheeled Coach/Road Rescue is recommending that you verify the lug size on the output cable of the secondary alternator. The correct lug size should be 2 ¼" and fit snugly around the alternator post. See attached photo. If this is not the correct size a new cable with the 2 ¼" lug must be installed.

Please contact Wheeled Coach/Road Rescue Customer Service Department at 800-932-7077, ext. 295 or 302. They will either direct you to our closest service center or send you a new cable and installation instructions.

If you have any questions please contact Fred Birchfield at 800-342-0720 ext. 265.