

## Technical Service Bulletin

#### 72 Seat adjustment switch sporadically inoperative

72 13 07 2018015/3 September 10, 2013. Supersedes Technical Service Bulletin Group 72 number 08-11 dated December 4, 2008 for reasons listed below.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment	
Q7	2007	000001-014796	Not Applicable	

### **Condition**

REVISION HISTORY				
Revision	Date	Purpose		
3	-	Revised header data (Updated customer codes)		
2	12/4/2008	Revised title to include Repair Group		

Seat adjustment switch for longitudinal, height, rake, and backrest is adjustment sporadically inoperative.

## **Technical Background**

Printed circuit board causes sporadic seat adjustment switch operation.

#### **Production Solution**

Improved seat adjustment switch.

#### **Service**

Replace the seat adjustment switch.



## Technical Service Bulletin

## **Warranty**

Claim Type:	Use applicable claim type. If vehicle is outside any warranty, this Technical Service Bulletin is informational only.				
Service Number:	7286				
Damage Code:	0040				
Labor Operations:	Driver's side trim remove and reinstall	7216 1900	50 TU		
	Front passenger's side trim remove and reinstall	7216 1905	90 TU		
	Seat adjust switch remove and reinstall	7286 1950	10 TU		
Diagnostic Time:	GFF	No allowance	0 TU		
	Road test prior to service procedure	No allowance	0 TU		
	Road test after service procedure	No allowance	0 TU		
	Technical diagnosis at dealer's discretion				
	(Refer to Section 2.2.1.2 and Audi Warranty Online for DADP allowance details)				
Claim Comment:	As per TSB #2018015/3				

All warranty claims submitted for payment must be in accordance with the *Audi Warranty Policies and Procedures Manual*. Claims are subject to review or audit by Audi Warranty.

## **Required Parts and Tools**

Part Number	Part Description	Quantity			
4L0959747 4PK	Switch for seat longitudinal-seat height-seat rake and backrest adjustment, left, sabre (black)	1			
-or-					
4L0959747A 4PK	Switch for seat longitudinal-seat height-seat rake and backrest adjustment, left, sabre (black)	1			
-or-					
4L0959748 4PK	Switch for seat longitudinal-seat height-seat rake and backrest adjustment, right, sabre (black)	1			



# Technical Service Bulletin

### **Additional Information**

All parts and service references provided in this TSB (2018015) are subject to change and/or removal. Always check with your Parts Department and service manuals for the latest information.