

Technical Service Bulletin



94 Headlight switch pressed in

94 13 12 2017566/4 March 29, 2013. Supersedes Technical Service Bulletin Group 94 number 09-23 dated August 12, 2009 for reasons listed below.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
A4/S4	2009 – 2015	All	N/A
A5/S5	2008 – 2015	All	
A5/S5 Cabriolet	2010 – 2015	All	
Q5	2009 – 2015	All	
A6	2012 – 2015	All	
A7	2012 – 2015	All	

Condition

REVISION HISTORY		
Revision	Date	Purpose
4	-	Revised header data (Added model years and A6/A7)
3	8/12/2009	Revised header data (Added A5 Cabriolet and Q5, new customer code)
2	11/13/08	Revised Title to include Repair Group

Headlight switch knob is pressed in. The switch functions correctly.

Technical Background

The headlight switch knob was designed with a normal position and a pushed-in position (Figures 1 and 2). This is a deliberate design feature designed to avoid injuries in the event of a collision.



Figure 1. The headlight switch knob, pushed in.



Figure 2. The headlight switch knob, in normal position.

Production Solution

Not applicable.

Service

1. Pull out the knob and return it to the original position.
2. Explain the safety feature to the customer.

Warranty

This TSB is informational only and not applicable to any Audi warranty.

Required Parts and Tools

Do not replace the switch as it will be debited.

Additional Information

All parts and service references provided in this TSB are subject to change and/or removal. Always check with your Parts Department and service manuals for the latest information.