

# Technical Service Bulletin

#### 85 Defroster outlet trim deformed

85 13 15 2033426/1 March 29, 2013.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment	
A4	2009 - 2012	000001 - 999999	Not applicable	
A4	2013	DN000001 – DN025065		
A4	2013	DA000001 – DA133001		
A5	2008 - 2012	000001 - 999999		
A5	2013	000001 - 033350		
A5	2013	900000 - 901377		
A5 Cab	2010 - 2012	000001 - 999999		
A5 Cab	2013	000001 - 006565		

#### **Condition**

The trim panel at the defroster vent on the instrument panel is deformed (Figure 1).



Figure 1. Deformed defroster vent trim panel.

# Audi

## Technical Service Bulletin

## **Technical Background**

The trim panel is composed of a material which expands in a moist condition. The instrument panel restricts this expansion which leads to deformation of the trim.

#### **Production Solution**

The attachment of the trim panel is improved.

#### **Service**

Replace the defroster vent trim panel.

### **Warranty**

Claim Type:	Use applicable claim type. If vehicle is outside any warranty, this Technical Service Bulletin is informational only.				
Service Number:	8553				
Damage Code:	0018				
Labor Operations:	Air outlet remove and reinstall	8557 1900	20 TU		
Diagnostic Time:	GFF	No allowance	0 TU		
	Road test prior to service procedure	No allowance	0 TU		
	Road test after service procedure	No allowance	0 TU		
Technical diagnosis at dealer's discretion (Refer to Section 2.2.1.2 and Audi Warranty Online for DADP allow			e details)		
Claim Comment:	As per TSB #2033426/1				

All warranty claims submitted for payment must be in accordance with the *Audi Warranty Policies and Procedures Manual*. Claims are subject to review or audit by Audi Warranty.



# Technical Service Bulletin

## **Required Parts and Tools**

Part Number	Part Description	Quantity
8T1819636 1DH	Trim for air vent – Agate grey	1
8T1819636 1GK	Trim for air vent – Kamut beige	1
8T1819636 6PS	Trim for air vent – Sabre (black)	1

#### **Additional Information**

All parts and service references provided in this TSB are subject to change and/or removal. Always check with your Parts Department and service manuals for the latest information.