

PSS 48 Power steering feels notchy

48 13 38 2033044/2 March 18, 2013. Supersedes Technical Service Bulletin Group 48 number 13-36 dated February 21, 2013 for reasons listed below.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment	
A4 / S4	2013	000001 - 999999	Not applicable	
A5 / S5	2013	000001 - 999999	Not applicable	
A5 Cab / S5 Cab	2013	000001 - 999999	Not applicable	
A6 / S6	2012 - 2013	000001 - 999999	Not applicable	
A7 / S7	2012 - 2013	000001 - 999999	Not applicable	

Condition

REVISION HISTORY					
Revision	Date	Purpose			
2	-	Revised header data			
1	02/21/2013	Initial publication			

- The customer states they have a comfort concern about the steering system. The steering works correctly but intermittently feels notchy.
- There is no loss of steering functionality.
- The concern may be more apparent in colder weather, and may improve with warmth or an ignition key cycle.
- No DTC is stored and no warning appears in the cluster.

ID Tip: This PSS TSB applies only to the comfort concern described in the condition of this PSS TSB. Please refer to the attached Information and Q&A document for guidance when handling each case.

^{© 2013} Audi of America, Inc.

All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.

Technical Service Bulletin



Technical Background

A solution is in development and will be made available as soon as possible.

The steering wheel is mechanically linked to the wheels of the vehicle, and there is no loss of steering functionality.

Refer to the attached Information and Q&A document for guidance when handling each case.

Production Solution

Open.

Service

- 1. Explain to the customer that a solution is forthcoming and that no repairs are necessary at this point. Do not replace any components for this condition since this will not resolve the customer's concern.
- 2. Create a PSS record in the PSS application via the hyperlink in Accessaudi.com (Figure 1) or Technical Assistance page in Elsa (Figure 2).




Figure 1. Related Sites section on Accessaudi.com landing page

© 2013 Audi of America, Inc.

All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.



Technical Service Bulletin

		Open Takets						
Access Code	Case Bunder	VM	Model	Model Year	Status			
There are no open tickets								
		Escalated Tackets						
Asses Code	Caser Humber	VM	Model	Model Tear	Status			
Nere are no escalabel Schetz								
	Contrast Alert Tackets							
Access Code	Case Mandeer	**	Model	Model Tear	States			
Gestifichet AUDI Seach								
VR is not populated.								
Neur of Operations								
Monday thru friday 8:36 AM to 7:86 PM ET				Follow the link before to Pending Service Solutions				
Team meeting every Monday			E	Pending Service Solutions				
BE PHI IN 2:30 PM ET								

Figure 2. Technical Assistance page

Warranty

This TSB is informational only and not applicable to any Audi warranty.

Additional Information

All parts and service references provided in this TSB are subject to change and/or removal. Always check with your Parts Department and service manuals for the latest information.

© 2013 Audi of America, Inc.

All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.