

Technical Service Bulletin



70 Noises from the instrument panel area

70 13 30 2033711/1 April 25, 2013.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
A4 / Allroad	2013	A000001 – A209596	Not applicable
A4 / Allroad	2013	N000001 – N040070	Not applicable

Condition

Squeak or rattle noises from the instrument panel area.

Technical Background

Due to the multiple components that comprise the trim assembly, the panel surrounding the instrument cluster, MMI display screen, etc. can create these noises over bumps or when flexing.

Production Solution

An improved instrument panel trim (Figure 1) is implemented in production.



Figure 1. Instrument panel trim.

Service

Replace the instrument panel trim.

Technical Service Bulletin



Warranty

Claim Type:	Use applicable claim type. If vehicle is outside any warranty, this Technical Service Bulletin is informational only.		
Service Number:	7018		
Damage Code:	0020		
Labor Operations:	Replace instrument panel trim	7018 9999	60 TU
Diagnostic Time:	GFF	No allowance	0 TU
	Road test prior to service procedure	0121 0002	10 TU
	Road test after service procedure	0121 0004	10 TU
	Technical diagnosis at dealer's discretion (Refer to Section 2.2.1.2 and Audi Warranty Online for DADP allowance details)		
Claim Comment:	As per TSB #2033711/1		

All warranty claims submitted for payment must be in accordance with the *Audi Warranty Policies and Procedures Manual*. Claims are subject to review or audit by Audi Warranty.

Required Parts and Tools

Part Number	Part Description	Quantity
8K1857186XX XXX	Trim (Use appropriate index and color code based on equipment variant)	1

Additional Information

All parts and service references provided in this TSB are subject to change and/or removal. Always check with your Parts Department and service manuals for the latest information.