

A PDF of this newsletter and previous ones can be found by logging in to ServiceNet and clicking on the [ElsaWeb Newsletter](#) section in the Technician References menu.

Audi Truth in Engineering 

Audi ElsaWeb Newsletter

Edition 22: February 4, 2013

Content

- [O.D.I.S. Feedback Submission](#)
- [Feedback Corner](#)
- [Technical Bulletins](#)
- [Campaigns](#)
- [Updates](#)
- [Repair Manuals](#)
- [Wiring Diagrams](#)
- [Suggestions](#)



O.D.I.S. Feedback Submission

When submitting a feedback concerning O.D.I.S. please make sure to use the feedback system within that application. The ODIS Support button is used to send a support request or to submit feedback for the Offboard Diagnostic Information System Service, as outlined in the Service Information document VOS-12-11 Offboard Diagnostic Information System Support Button Overview, which is available on ServiceNet. Submitted feedback should include a diagnosis log using the most current version of software, a screen print of the issue (where possible) and a thorough description of the issue.

Feedback Corner

This week's feedback is from Paul, regarding a 2013 A8 Repair Manual. He stated:

"Fault P0106 in DTC table tells you to check G31. This vehicle is equipped with G71 MAP sensor and two charge air pressure sensors. I believe this info may be inaccurate."

This feedback was reviewed by the Service Information Team and was fixed. We really appreciate you sending in feedback to help improve the quality of the repair information.

Feedback Status		
New	Completed	To Factory
16	21	5

*Please note that this feedback feature is not the place to obtain technical assistance for Audi vehicles, or to report potential issues you may have experienced with a vehicle. If you require assistance in repairing or diagnosing a vehicle issue, or wish to report a technical issue, please create an Audi Technical Assistance ticket and contact the Audi Technical Assistance at (800)-678-2389.

[Back to top](#)

Technical Bulletins

01 MIL on cylinder misfires - DTCs P0300 - P0308 (2032222/2)		
Model(s)	Year	Vehicle Specific Equipment
RS 5	2013	Not Applicable
<ul style="list-style-type: none">• MIL may illuminate.• DTCs P0300, P0301, P0302, P0303, P0304, P0305, P0306, P0307 and/or P0308 for misfire may be stored in the DTC memory.• Replacing the ignition coils and spark plugs does not fix the problem.<ul style="list-style-type: none">• No drivability issues are present.		

01 MIL on DTC P00AF Stored in ECM Fault Memory (2030609/2)

Model(s)	Year	Vehicle Specific Equipment
A3 TDI	2013	All in North American market
MIL on. Workshop Findings: DTC P00AF (Turbocharger/Supercharger Boost Control "A" Module Performance) Stored in ECM Fault Memory. "		

37 Gearbox warning light on - Faults P0605 and/or P17EC stored in Selector lever module 81 (2028561/4)

Model(s)	Year	Vehicle Specific Equipment
A8, A8L, A8, W12	2010-2013	Electronic shift module 81
<ul style="list-style-type: none">• There is no customer complaint about the gearbox.<ul style="list-style-type: none">• The gear lever display flashes.• The message "gearbox problem, journey can be continued with restrictions" is shown.• The entry P0605 or P17EC is logged under the diagnosis address 81- Selector lever.		

PSS 46 TT RS brake noise (2032729/1)

Model(s)	Year	Vehicle Specific Equipment
TT RS	2012-2013	All
The customer may complain of a high-pitched squeal or squeak from the brake system when braking at slow speeds, even though the brake pads and discs still have a significant life left.		

85 Instrument panel vents cannot be adjusted(2032579/1)

Model(s)	Year	Vehicle Specific Equipment
Q7	2012>	Not Applicable
The air distribution fins in either of the outer instrument panel vents do not adjust. The fins may be broken or loose and cause a rattling sound. The fins may also be missing.		

91 BOSE AudioPilot volume fluctuates unnaturally (2029197/4)

Model(s)	Year	Vehicle Specific Equipment
A3	2011-2013	BOSE Sound System
Customer states volume fluctuates unnaturally. This may be described as: <ul style="list-style-type: none">• Significant increases in Bass or Treble levels shortly after startup, in conjunction with Park Aid, or during normal driving.• Fluctuations in background “hissing” during a phone call. Only applies to vehicles equipped with BOSE sound system (PR No. 8RY)		

PSS 91 MMI3G+ Google Earth will not load - Zug 566 (2032849/1)

Model(s)	Year	Vehicle Specific Equipment
A8	2011-2013	MMI 3G+ with Audi Connect
A6/A7	2012-2013	MMI 3G+ with Audi Connect
Q7	2012-2013	MMI 3G+ with Audi Connect
A4/A5/Q5	2013	MMI 3G+ with Audi Connect
The Google Earth map will not load. The display shows an active data connection, and “Google” is almost fully white. Workshop Findings: <ul style="list-style-type: none">• Customer has active Audi Connect subscription.• All other Audi Connect functions operate normally.• The concern only occurs if the vehicle is started in a 2G cellular zone. The system operates normally if the vehicle is started in a 3G cellular zone.		

PSS 91 MMI sound system "pop" and no audio (2032706/1)

Model(s)	Year	Vehicle Specific Equipment
A4	2011-2013	MMI 3G(+)
Allroad	2013	MMI 3G(+)
A5/RS5	2011-2013	MMI 3G(+)
A5 Cab	2011-2013	MMI 3G(+)
A6/S6	2011-2013	MMI 3G(+)

A7/S7	2012–2013	MMI 3G(+)
A8/S8	2011–2013	MMI 3G(+)
Q5	2011–2013	MMI 3G(+)
Q7	2011–2013	MMI 3G(+)
<p>Customer complains of a “popping” noise from the radio followed by 10-15 seconds of no audio. The concern can happen in any audio source. The following conditions must apply:</p> <ul style="list-style-type: none"> • Vehicle is equipped with MMI 3G or MMI 3G+ infotainment systems. • Vehicle is not equipped with Bose or Bang & Olufsen sound systems. • An ignition cycle is not required for audio to resume. 		

PSS 96 Lane Change Assistant sporadically inoperative (2032687/1)		
Model(s)	Year	Vehicle Specific Equipment
A6, A7	2012–2013	Lane Change Assistant
<p>Customer complaint: Audi Lane Change Assistant deactivates or is sporadically inoperative Workshop Findings:</p> <ul style="list-style-type: none"> • Audi Lane Change Assistant can be activated without issue One or both of the following DTCs is stored in the Lane Change Assistance control module J769 (3C): <ul style="list-style-type: none"> • DTC 02853 (Lane Change Assistance Warning Lamp -K233- Open/Short Circuit to B+) • DTC 02854 (Lane Change Assistance Warning Lamp -K234- Open/Short Circuit to B+) 		

96 False warning by Audi Side Assist (2028809/4)		
Model(s)	Year	Vehicle Specific Equipment
A6, A7	2012	Audi Side Assist
<p>Customer complains that Audi Side Assist is providing false warnings (no vehicle is present). Concern may or may not be duplicated.</p> <p>No DTCs are present in the Audi Side Assist system.</p>		

[Back to top](#)

Campaigns

No new Campaigns in ElsaWeb. [Back to top](#)

Updates

No new Updates in ElsaWeb. [Back to top](#)

Repair Manuals

Repair Manuals			
Elsa Name	Model	Book Updated	Reason
4L	Q7 2007>	Communication	Feedback #720663
8F	A5/S5 Cabriolet 2010>	Heating, Ventilation and Air Conditioning	Factory Update
8K2	A4 2009>, S4 2010>	Heating, Ventilation and Air Conditioning	Factory Update
8K5	A4 Avant 2009>	Heating, Ventilation and Air Conditioning	Factory Update
8KH	Allroad 2013>	Heating, Ventilation and Air Conditioning	Factory Update
8R	Q5 2009>	Heating, Ventilation and Air Conditioning	Factory Update
8T	A5/S5 Coupe 2008>	Heating, Ventilation and Air Conditioning	Factory Update
8F	A5/S5 Cabriolet 2010>	Maintenance Procedures	Factory Update
8T	A5/S5 Coupe 2008>	Maintenance Procedures	Factory Update
4G2	A6 Sedan 2012>	Electrical Equipment	Factory Update
8P	A3 2006>	Engine Mechanical	Feedback #753701
4G	A6 Sedan, A7 Sportback 2012>	Engine Mechanical	Feedback #722311, 743678

[Back to top](#)

Wiring Diagrams

No new Wiring Diagrams in ElsaWeb. [Back to top](#)

Suggestions:

Please send comments or suggestions to: aoa.WorkshopInformation@audi.com

[Back to top](#)

© 2012 Audi of America, Inc. All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.