

Technical Service Bulletin



46 Brake noise

46 13 49 2033838/1 July 22, 2013.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
RS5	2013	000001 - 902740	Without ceramic brakes
RS5 Cab	2013	000001 - 900473	Without ceramic brakes

Condition

Customer may report hearing brake squeal from the front brakes. The sound may be more prevalent during cold weather.

Technical Background

Not applicable.

Production Solution

New brake pads introduced in production from April 1, 2013:

- RS5 from VIN FRDA902740
- RS5 Cab from VIN FHDN900473

Service

Install updated front brake pads (Part Number: **8T0698151C**). See *ElsaWeb*>> *Repair Manual*>> *Chassis*>> *46 Mechanical Components* >> *Removal and Installation* >> *Front Brakes, 1LM* >> *Brake Pads*.

Technical Service Bulletin



Warranty

Claim Type:	Use applicable claim type. If vehicle is outside any warranty, this Technical Service Bulletin is informational only.		
Service Number:	4636		
Damage Code:	0020		
Labor Operations:	Wheels remove & reinstall	4405 2000	20 TU
	Brake pads, front remove & reinstall	4636 2050	50 TU
Diagnostic Time:	GFF	No allowance	0 TU
	Road test prior to service procedure	0121 0002	10 TU
	Road test after service procedure	0121 0004	10 TU
	Technical diagnosis at dealer's discretion (Refer to Section 2.2.1.2 and Audi Warranty Online for DADP allowance details)		
Claim Comment:	As per TSB #2033838/1		

All warranty claims submitted for payment must be in accordance with the *Audi Warranty Policies and Procedures Manual*. Claims are subject to review or audit by Audi Warranty.

Required Parts and Tools

Part Number	Part Description	Quantity
8T0698151C	1 set of brake pads for disc brakes	1 set

Additional Information

All parts and service references provided in this TSB (2033838) are subject to change and/or removal. Always check with your Parts Department and service manuals for the latest information.