

# Audi of America, Inc.



Date: August 27, 2013

To: Audi Dealer Principal, Service Manager, and Parts Manager

From: Audi Product Compliance

Subject: Revision to Update 24Z6  
Model Year 2013 – 2014 Audi Vehicles Equipped with 3.0 L Engine  
Manifold Actuator

Dear Audi Dealer Principal, Service Manager, and Parts Manager:

This communication is to inform you of a revision to Update **24Z6**.

We have revised the bulletin for this Update. We have included information on the ball head torx bit that is required to access the screws. We have also included tips to help catch a screw that may be dropped during the repair.

Please review the revised procedure that is published on ServiceNet and ElsaWeb.

Audi of America, Inc.  
3800 Hamlin Road  
Auburn Hills, MI 48326  
+1 248 754 5000  
[www.audiusa.com](http://www.audiusa.com)