

Technical Service Bulletin



94 Dimmer cap missing from headlight switch

94 13 26 2031378/2 August 1, 2013. Supersedes Technical Service Bulletin Group 94 number 12-93 dated October 25, 2012 for reasons listed below.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
A6 (C7)	2011 - 2013	All	Not Applicable

Condition

REVISION HISTORY		
Revision	Date	Purpose
2	-	Revised header data (added model years)
1	10/25/2012	Initial publication

Cap on dimmer knob (light switch) has fallen off and cannot be found (Figure 1).



Figure 1. Dimmer knob on main light switch

Technical Background

Not applicable.

Production Solution

Not applicable.

Technical Service Bulletin



Service

Replace missing cap. Do *not* replace the main light switch. Switches replaced for this condition will be charged back.

Warranty

Claim Type:	Use applicable claim type. If vehicle is outside any warranty, this Technical Service Bulletin is informational only.		
Service Number:	9405		
Damage Code:	0010		
Labor Operations:	Replace Dimmer cap	9405 1999	10 TU
Diagnostic Time:	GFF	No allowance	0 TU
	Road test prior to service procedure	No allowance	0 TU
	Road test after service procedure	No allowance	0 TU
	Technical diagnosis at dealer's discretion (Refer to Section 2.2.1.2 and Audi Warranty Online for DADP allowance details)		
Claim Comment:	As per TSB #2031378/2		

All warranty claims submitted for payment must be in accordance with the *Audi Warranty Policies and Procedures Manual*. Claims are subject to review or audit by Audi Warranty.

Required Parts and Tools

Part Number	Part Description	Quantity
4G0941158B	Cap for dimmer switch	1

Additional Information

All parts and service references provided in this TSB (2031378) are subject to change and/or removal. Always check with your Parts Department and service manuals for the latest information.