Das Auto.

Tech Tips

TT 91-13-01

Date: February 8, 2013

2012-2013 CC, Eos, Passat, Tiguan, Equipped With RNS-510 Radio—Unit Start-Up and Boot-Up Operation

The navigation unit may be slow to respond at times when memory use is high. This may include boot-up time after vehicle start up or times when multiple features are in use. Symptoms may be described as "Locks Up", "Freezes", or "No Response". Switching modes (i.e. broadcast radio to SAT), Rear View Camera or soft-touch keys could be affected. The operation described above is considered a product characteristic. Warranty claims submitted with described operation may be denied.

© 2013 Volkswagen Group of America, Inc.

All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Volkswagen Group of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.