

Tech Tips

TT 87-11-03

Date: December 16, 2011

2012-2013 Passat with Dual Zone Climatronic – One Zone
Colder / Warmer Than the Other

February 15, 2013: Update to applicability and information.

For concerns of one zone with no heat or blowing colder / warmer than the other on vehicles with dual zone Climatronic, first check the linkage between the actuator motor **V158** and the left temperature blend door for proper **installation, and/or** damage. **Linkage is number labeled 2 in the picture below.** If the linkage is ok, proceed with normal diagnostics such as fault code and refrigerant charge checks.

