



# Tech Tips

TT 24-13-01

Date: February 22, 2013

## 2009-2013 Tiguan – ECM Software Update Tip

If instrument cluster does not communicate with the scan tool after completing an ECM software update, it is recommended to perform a capacitive discharge before replacing parts or performing any additional diagnosis.