



Service Bulletin

PRELIMINARY INFORMATION

Subject: Diagnostic Tip for DTCs U183E, U184B, U184D and U0140 Set After Vehicle Has Been in Transport Mode

Models: 2014 Chevrolet Spark EV

Condition/Concern

Technicians may find DTCs U183E, U184B, U184D and U0140 stored in history.

This condition may be caused by the vehicle left in transport mode.

Recommendation/Instructions

Clear the DTCs and turn off the transport mode. For information regarding turning the transport mode off, refer to the latest version of Bulletin Number 11-08-49-001.

Warranty Information

For vehicles repaired under warranty, use:

Labor Operation	Description	Labor Time
4069929	Electrical Controls – Labor Only (Clearing DTCs)	Use Published Labor Operation Time

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION