



# Service Bulletin

## PRELIMINARY INFORMATION

**Subject:** Accessory Fog Lamp Inoperative

**Models:** 2013 Chevrolet Cruze  
Built Prior to March 25, 2013

*This PI is being revised to add a build date and information to the Recommendation/Instructions. Please discard PI0910A.*

### Condition/Concern

Some technicians may notice the accessory fog lamps are inoperative after installation.

This condition may be caused by the production body control module (BCM) not automatically enabling the fog lamp function.

### Recommendation/Instructions

The BCM software will need to be updated. Reflash the BCM with the newest available calibration file.

**Note:** The Techline Customer Support Center (TCSC) will no longer need to be contacted to manually update the vehicle.

### Warranty Information

For vehicles repaired under warranty, use:

Labor Operation	Description	Labor Time
N4808	Body Control Module Reprogramming with SPS	Use Published Labor Operation Time

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION