



Service Bulletin

PRELIMINARY INFORMATION

Subject: Flex Fuel Sensor and Bracket Part Change

Models: 2013 Chevrolet Impala

This PI is being revised to update the build dates and Parts Information. Please discard PI0932.

Due to a running change in production where 2012 flex fuel sensors and brackets were installed on some 2013 vehicles, the following service information is being provided.

Vehicles Built Between February 26, 2013 and April 8, 2013

These vehicles were built with a 2012 flex fuel sensor and bracket. If a flex fuel sensor requires replacement, the sensor only needs to be replaced with the part number listed below.

Parts Information

Part Number	Description
13577379	SENSOR, FLEX FUEL

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION