



<b>Countries:</b>	CANADA, UNITED STATES	<b>Document ID:</b>	IK1200909
<b>Availability:</b>	ISIS	<b>Revision:</b>	18
<b>Major System:</b>	ENGINES	<b>Created:</b>	5/19/2013
<b>Current Language:</b>	English	<b>Last Modified:</b>	10/30/2013
<b>Other Languages:</b>	NONE	<b>Author:</b>	Charles Schroeder
<b>Viewed:</b>	6615		

[Less Info](#)

Hide Details

Coding Information

<b>Copy Link</b> 	<b>Copy Relative Link</b> 	<b>Bookmark</b>  <a href="#">View My Bookmarks</a>	<b>Add to Favorites</b> 	<b>Print</b> 	<b>Provide Feedback</b> 	<b>Helpful</b>  40	<b>Not Helpful</b>  11
----------------------	-------------------------------	--	-----------------------------	------------------	-----------------------------	--------------------------	------------------------------

**Title: High Pressure Turbocharger Service Plan Information**

**Applies To: 2010 MaxxForce 11 and 13, 2013 MaxxForce 13 HDOBD, 2013 N13 with SCR**

## PURPOSE

This plan will provide all information needed to diagnose and repair the high pressure turbocharger ad air management system on a 2010 MaxxForce 11 / 13.

Launch the Service Plan from the iApprove Tab located in the Vehicle Information page of the Service Portal. [Click Here](#) for a screen shot of the information.

The Service Plan will guide you through the following:

## TRIAGE

Performed at write-up:

1. [Printable TRIAGE FORM](#)
2. Interrogate the driver for vehicle operational and maintenance details.
3. Check and document all vehicle Diagnostic Trouble Codes
4. Check vehicle repair and warranty history.
5. Check for all open or incomplete campaigns.
6. Check Calibration Scorecard.

## STEP BY STEP WORK FLOW (DECISION TREE)

1. A [Printable FLOW CHART](#) of all steps, diagnostics and repairs.

## PARTS

1. List of parts that may be required for repair:

PART NUMBER	DESCRIPTION	QUANTITY
2511792C91	Kit, HP Turbo Cartridge	1
3005741C91	Oil Supply Line	1
1820907C2 (If needed)	O-Ring Seal	1

## TOOLS

1. KL9007NAV - Navistar Coolant Management Tool
2. General Hand / Air Tools

## WARRANTY INFORMATION

- Effective with warranty claims for all models 8/29/2013 and later. SRT's for Labor Operations not listed should be claimed according to current Warranty and Policy procedures.

Turbocharger HP Center Section Service Plan SRT's ProStar+ With EPA 2010		
SRT Code	SRT Hours	Description
R12-6135U-21	1.9	TURBOCHARGER H.P CENTER SECTION, REPLACE
A12-3510A-20	0.2	ELECTRONIC CONTROL MODULE (ECM OR ECM/IDM) - ENGINE, PROGRAM

Turbocharger HP Center Section Service Plan SRT's TranStar With EPA 2010		
SRT Code	SRT Hours	Description
Q12-6135U-21	1.9	TURBOCHARGER H.P CENTER SECTION, REPLACE
Q12-6135U-1	0.6	Add - on: Engine Cover, Remove and Reinstall
A12-3510A-20	0.2	ELECTRONIC CONTROL MODULE (ECM OR ECM/IDM) - ENGINE, PROGRAM

Turbocharger HP Center Section Service Plan SRT's WorkStar With EPA 2010		
SRT Code	SRT Hours	Description
N12-6135U-21	1.9	TURBOCHARGER H.P CENTER SECTION, REPLACE
A12-3510A-20	0.2	ELECTRONIC CONTROL MODULE (ECM OR ECM/IDM) - ENGINE, PROGRAM

Effective with warranty claims for all models 10/07/2013 and later. SRT's for Labor Operations not listed should be claimed according to current Warranty and Policy procedures.

 Hide Details

Feedback Information

Viewed: 6614

Helpful: 40

Not Helpful: 11

Staff ID	Client ID	Comments	Created Date

U022080	You received the following feedback From: U022080 - Daniel Modesto Email Address: SMTP: {daniel.modesto@navistar.com}daniel.modesto@navistar.com Feedback: The 11L uses a different turbo and does not have a center section available, so the parts list is inaccurate and only applies to 13L.	10/30/2013 1:03:11 PM
---------	--	--------------------------

Copyright © 2013 Navistar, Inc.