



Countries:
Availability:
Major System: ENGINES
Current Language: English
Other Languages: NONE
Viewed: 206

Document ID: IK1200962
Revision: 0
Created: 10/1/2013
Last Modified: 10/1/2013
Author: Octavio Ortiz

[Less Info](#)

Hide Details

Coding Information

Copy Link	Copy Relative Link	Bookmark	Add to Favorites	Print	Provide Feedback	Helpful	Not Helpful
		 View My Bookmarks				 2	 0

Title: 2007-09 I6 Cold Side EGR Cooler Replacement

Applies To: 2007-09 EPA MaxxForce DT, 9, 10

DESCRIPTION

The cold side EGR cooler requires specific criteria to be met in order for it to be granted warranty approval. EGR cooler replacement is **NOT** based solely on appearance. The cold side EGR cooler should **NOT BE REPLACED** unless the following is met:

A. Cooler fails KLINE 20020 coolant pressure test (*cooler leaks*)

– All returns will be pressure tested upon receipt

OR

B. DTC 2389 - EGR flow insufficient - possible plugged system is stored in the ECM

– Verified via Health Report

PROCEDURE

COOLER LEAK

- Pressure test EGR cooler.
- Follow directions included in the EGR Leak Detection Kit (KLINE 20020).

DTC STORED

- Follow the 2007 MaxxForce DT, 9, 10 Engine Diagnostic Manual (EPA 07) (Formerly EGES-455 - **0000002581**) for DTC 2389.

A case file is not needed for authorization of cooler R&R when the above criteria applies.

[Hide Details](#)**Feedback Information**

Viewed: 205

Helpful: 2

Not Helpful: 0

No Feedback Found

Copyright © 2013 Navistar, Inc.