



Countries: AUSTRALIA, BRAZIL, CANADA, UNITED STATES, MEXICO, PUERTO RICO, SOUTH AFRICA

Document ID: IK0800173

Availability: ISIS, Bus ISIS, FleetISIS

Revision: 5

Major System: FUEL SYSTEMS

Created: 8/28/2007

Current Language: English

Last Modified: 12/23/2013

Other Languages: [Français](#), [Español](#)

Author: Frank Amstadt

Viewed: 7287

[Less Info](#)

Hide Details

Coding Information

Copy Link	Copy Relative Link	Bookmark	Add to Favorites	Print	Provide Feedback	Helpful	Not Helpful
		 View My Bookmarks				 1635	 984

Title: Fuel Filter Indicator Light is Illuminating with no Engine Problems International I-6

Applies To: 2004 and up International I-6 (DLC II)

DESCRIPTION

Use MasterDiagnostics to monitor the fuel pressure. A 372 code will be set by the engine ECM if fuel pressure drops to between 44psi and 51psi depending on engine load and engine speed conditions. If fuel pressure is dropping and a 372 code is setting, clean the fuel pressure regulator and retest. If the condition is still present, replace the fuel pressure regulator.

For location of the fuel pressure regulator [click here](#).

For electrical troubleshooting information, [click here](#).

Hide Details

Feedback Information

Viewed: 7286

Helpful: 1635

Not Helpful: 984

Staff ID	Client ID	Comments	Created Date
	DY08955	You received the following feedback From: dy08955 - David Gabrielle Email Address: gabe396@aol.com Job Classification: SE008, Service Technician Dealer: TRUCK KING INTL IDEALEAS Feedback: The two links: For location of the fuel pressure regulator click here. For electrical troubleshooting information, click here Do not work.	12/26/2013 5:51:07 AM