



Countries:	CANADA, UNITED STATES, PUERTO RICO	Document ID:	IK1500027
Availability:	ISIS	Revision:	3
Major System:	FUEL SYSTEMS	Created:	11/28/2007
Current Language:	English	Last Modified:	12/23/2013
Other Languages:	Français , Español ,	Author:	Frank Amstadt
Viewed:	2313		

[Less Info](#)

Hide Details

Coding Information

Copy Link	Copy Relative Link	Bookmark	Add to Favorites	Print	Provide Feedback	Helpful	Not Helpful
		 View My Bookmarks				 248	 532

Title: Fuel Transfer Pumps on 4000 Models built at Garland between 5/22/07 and 11/20/07 May be Installed Backwards

Applies To: DuraStar (4300 and 4400) Models

DESCRIPTION

There are some DuraStar models (4300 and 4400 models) built at Garland Assembly (J in the 11th position of the VIN) built between 5/22/07 and 11/20/07 that the fuel transfer pump maybe installed backwards. When this happens the transfer pump will pump from the right tank (draw tank) to the left tank.

SYMPTOMS

- Running out of fuel
- Fuel not transferring

RESOLUTION

To correct the issue remove the transfer pump from the fuel lines and turn it 180 degrees so it draws from the left fuel tank.



Bad



Good



Hide Details

Feedback Information

Viewed: 2312

Helpful: 248

Not Helpful: 532

No Feedback Found

Copyright © 2014 Navistar, Inc.